

# HAZARD DATA

RAMGARH (2013)

## History of Hazards

Sr.	Type of Hazard	Date of Occurrence	Block Effected	Villages effected	Casualty		
	Lightening	1/13-14	Ramgarh	Parsotiya Chitarpur	Death	1	
					Injured	1	
	Fire	1/13-14	Ramgarh	Larikala	House Damaged (i) Fully (ii) Partial	1	
					Crop Damaged		
					Cattle Loss		
					Any other loss		

## Ramgarh Block

Section office - Ramgarh.

Sub divisional office - Ramgarh No. – 1, Ramgarh.

Nodal officer :- Er. Vijay Kumar Mishra (A.E).

Mobile No. 9472768035

JE Vimlendu Prasad..

Mobile No 9431791931

Supporting Staff : - BRC - 01 no. Name Sri Ranjit Saw Mobile 7352546580  
CRC – 01 Nos.(i) Sri M.K.Ravi Mobile no. 8252228231

Repairing Gang - 1 No.

Tube well Mistry – 01 No. Surendra Kumar Mishra Mobile No. 8809255942

Tube well Khalasi – 3 Nos.

Hand Pumps :- 848

Surface well :- 10

PWS :- 10

# HAZARD DATA

PATRATU (2013)

## History of Hazards

Sr.	Type of Hazard	Date of Occurrence	Block Effected	Villages effected	Casualty		
	Heavy Rain	Rainy Season	Patratu	Several villages	Death		
					Injured		
					House Damaged	143	
					(i) Fully	155	
					(ii) Partial		
					Crop Damaged		
					Cattle Loss		
					Any other loss		

## Patratu Block

Section office - Patratu.

Sub divisional office - Patratu, Ramgarh.

Nodal officer :- Er. Anil Kumar

Mobile No. 9122006749

(I). JE Prem BandhanKachhap

Mobile No 9431987223

(ii) JE. Chand Kumar Hembrom

Mobile No. 7250247376

Supporting Staff :- BRC - 01 no. Name Sri Ranjit Kumar Mobile 9431547911

CRC – 02 Nos.(i) Sri Janardan Munda Mobile no. 8521445900

(ii) Sri Rameshwar Mahto Mobile no. 9661277893

(iii) Sri Sanjay Kumar Mobile no. 9431548123

Repairing Gang - 1 No.

Tube well Mistry – 01 No. Jagan Ram Mobile No. 7352756792

Tube well Khalasi – 2 Nos.

Hand Pumps :- 2548

Surface well :- 49

PWS :- 01

MRWS.:- 06.

AVAILABILITY OF TANKER :- 9 Nos of block campus of Patratu

## HAZARD DATA

GOLA (2013)

### History of Hazards

Sr.	Type of Hazard	Date of Occurrence	Block Effected	Villages effected	Casualty		
1	Accident	21-4-2013	Gola	1	Death	01+4+01	
2	Road Accident	21-1-13 to 02-4-13	Gola	3	Injured		
					House Damaged (i) Fully (ii) Partial		
3	Lightening	25-6-13	Gola		Crop Damaged		
					Cattle Loss		
					Any other loss		

### Gola Block

Section office - Gola.

Sub divisional office - Ramgarh No. – 2, Ramgarh.

Nodal officer :- Er. Sunil Khalkho (A.E).

Mobile No. 9431904915

JE Surendra Prasad Singh.

Mobile No 8271698580

Supporting Staff : - BRC - 01 no. Name Sri Suresh Kumar Mobile 8409559557

CRC – 02 Nos.(i) Sri Mukesh Prasad Mobile no. 9572971947  
(ii) Sri Ajoy Kumar Mobile no. 8409748085

Repairing Gang - 1 No.

Tube well Mistry – 01 No. Shahabuddin Mobile No. 9955890042

Tube well Khalasi – 3 Nos.

Hand Pumps :- 1814

Surface well :- 32.

PWS :- 18

# HAZARD DATA

MANDU (2013)

## History of Hazards

Sr.	Type of Hazard	Date of Occurrence	Block Effected	Villages effected	Casualty		
1	Road Accidents	2013	Mandu		Death	44	
2	Lightening	2013	Mandu		Injured	66	
					House Damaged	-	
					(i) Fully	17	
					(ii) Partial		
					Crop Damaged	-	
					Cattle Loss	9	
					Any other loss	-	

## Mandu Block

Section office - Mandu

Sub divisional office - Ramgarh No. – 2, Ramgarh.

Nodal officer :- Er. Sunil Khalkho (A.E).

Mobile No. 9431904915

JE . Anand Murti Dixit

Mobile No 9955555398.

Supporting Staff :- BRC - 01 no. Name Sri Sanjay Kumar Kushwaha Mobile 9905135068

CRC – 03 Nos.(i) Smt. Pramila Devi Mobile no. 7352878881

(ii) Kumari Anjani Mobile no. 8651435841

(iii) Shahzada Ushmaan Mobile no. 9386061932

Repairing Gang - 1 No.

Tube well Mistry – 01 No. Ramlal Mahto Mobile No. 9852378439

Tube well Khalasi – 3 Nos.

Hand Pumps :- 2705

Surface well :- 63.

PWS :- 08.

AVAILABILITY OF TANKER :-9 Nos of at block campus of Mandu.

**Dulmi Block**

Section office - Ramgarh

Sub divisional office - Ramgarh No. – 1, Ramgarh.

Nodal officer :- Er. Vijay Kumar Mishra (A.E).

Nodal officer :- Er. Vijay Kurmar Mishra (A.E).

Mobile No. 9472768035

JE Vimlendu Prasad.

Mobile No 9431791931

Supporting Staff : - BRC - 01 no. Name Sri Jagarnath Mahto Mobile 9905313501  
CRC – 01 Nos. Sri Kamlesh Kumar Mobile no. 9905716590

Repairing Gang - 1 No.

Tube well Mistry – 01 No. Surendra Kumar Mishra Mobile No. 8809255942

Tube well Khalasi – 3 Nos.

Hand Pumps :- 775

Surface well :- 18

PWS :- 11

**Chitarpur Block**

Section office - Ramgarh

Sub divisional office - Ramgarh No. – 1, Ramgarh.

Nodal officer :- Er. Vijay Kurmar Mishra (A.E).

Mobile No. 9472768035

JE Vimlendu Prasad.

Mobile No 9431791931

Supporting Staff : - BRC - 01 no. Name Sri Om Nath Mahto Mobile 8084935355  
CRC – 01 No Name. Sri Aqbal Hussain Mobile no. 8409218974

Repairing Gang - 1 No.

Tube well Mistry – 01 No. Surendra Kumar Mishra Mobile No. 8809255942

Tube well Khalasi – 3 Nos.

Hand Pumps :- 744

Surface well :- 18.

PWS :- 07